Building/Year built: Scotts Valley CC Team: Shelley Zuniga, Dana Esposito

Date: 11/9/15 Job#: R15025

CITE **ELEMENT: PARKING** YES NO n/a NOTES

208.2	Parking Spaces: Parking Lots and Parking Structures are required to provide a minimum number of accessible parking spaces located on an accessible route and as close as possible to the accessible building entrance. If there are multiple parking areas, the required numbers of accessible parking spaces are based on each individual lot. *Does the lot meet the minimum number of accessible parking spaces per chart below? 1 to 25: 1	X		Total # of standard spaces: 86 Total # of accessible spaces: 4
208.3.1	Are the spaces located on the Shortest Accessible Route from the accessible parking space to an accessible entrance? (Dispersion: where parking sorres more than one accessible entrance disperse the	Х		
	(Dispersion: where parking serves more than one accessible entrance, disperse the accessible parking spaces so located on the shortest accessible route to each entrance.)			
502	The space:			
11B-502.2	Is the vehicular space 216" (18') long, 108" (9 feet) wide, and is the access aisle 60" (5 feet) wide and extend the full length of the space?	Х		
11B-502.3.3	Are access aisles marked with a blue painted border around the perimeter and the area within marked with diagonal lines spaced 36" on center in a contrasting color to the surface (preferred blue or white) and having the words NO PARKING painted in white on aisle, min of 12" high		Х	Lacks no parking on AA by CC (CC84)
11B-502.6.4	Is the stall painted in blue paint (or suitable contrast) and designated with the symbol of access (white icon on blue background) 36" X 36" big and centered on space?	Х		
502.2	Is there at least one van parking space (12 feet wide with a 5 foot wide access aisle located on the passenger side OR 9' and 8')?	Х		

Building/Year built: Scotts Valley CC Team: Shelley Zuniga, Dana Esposito

Date: 11/9/15 Job#: R15025

CITE	ELEMENT: PARKING	YES	NO	n/a	NOTES
502.5	Is there 98" of vertical clearance for van designated parking at the space and from parking entry to the space?	Х			
502.4	Is the slope in the stall or access aisle no greater than 1:48 in any direction? (2.08%)		Х		Stall 1: 3.5% (CC87, CC88) AA: 3% (CC85, CC86) Stall 2: 3.3% at drain (CC89, CC90) Stall at gardens: 4.2% (CC93, CC94); 2.4% AA (CC97, CC98)
502.3.4	Are all of the access aisles clear of the vehicular way? (doesn't overlap vehicular way)	Х			
502.4	Is the parking stall and access aisle compliant with 302; (CIL, gaps, surface firm, stable and slip resistant)?		Х		2 nd stall has drain (<u>CC90</u>)
502.6 11B-502.6.2	Is there a compliant sign for the accessible parking/van space(s) with the international symbol of accessibility, and Violation Sign stating a \$250.00? (exempt if 4 or less parking spaces; 216.5, exc. 1)		Х		
502.6	Is the bottom edge of the lowest sign 60" agl, measured from the parking surface; or 80" if in the EAR?		Х		Stall 1 too low at 50" (CC91)
11B-502.6.1	Is signage reflectorized and have a min area of 70"?		Х		
208.2.4	Is there a van accessible sign on at least one space?	х			
11B-502.8	Is there additional signage posted conspicuously stating: "Unauthorized vehicles parked in designated accessible spaces not displaying distinguishing placards or special license plates issued for persons with disabilities will be towed away at the owner's expense. Towed vehicles may be reclaimed at: or by telephoning"		X		
502.3	Do the Access Aisles connect the accessible parking space to an accessible entrance? (Access Aisles can be located on either side of the vehicle, except for angled parking, then it must be on the passenger side.)	Х			
502.7 11B-502.7.1	Are parking spaces/access aisles designed so that cars and vans, when parked, cannot obstruct the required CW of adjacent accessible routes Are wheel stops provided to prevent cars overhanging into AR?	X			

Rev. 04/9/14